


Firmware version : MD9600-REC-D03.28.bin

Programming software: V1.18

Press P1+ Alarm key(red key) to turn on MD-9600, display blinks and open upgraded software



And then write upgraded file named Upgraded software for scanning function into radio, the radio will be upgraded as following:



正在升级软件.....

BOOT Download

User Program

ID